


FIG. 1



009060-18855560

FIG. 2




FIG. 3




FIG. 4




[illegible]

FIG. 5



5 / 22  
FIG. 6



009060-18855960

FIG. 7




FIG. 8








FIG. 10






FIG. 11



10/22

FIG. 12



009060-1885960

FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 17





FIG. 18





17/22  
FIG. 19




FIG. 20




FIG. 21

-1	-1	-1
-1	9	-1
-1	-1	-1

FIG. 22





FIG. 23

PRECISE-BALANCE-CENTER-DETERMINATION SUBROUTINE  
(S5100)







FIG. 25



22/22

